

Message

---

**From:** O'Loughlin, Connor [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=D1F369DA6C9547ED90366BFB7C59510B-OLOUGHLIN,]  
**Sent:** 3/1/2021 6:54:55 PM  
**To:** Taylor, Daniel [taylor.daniel@epa.gov]  
**Subject:** RE: Blades- MW1,2,3  
**Attachments:** Ref. 88 Blades final report.pdf; Ref. 49 Well Survey BLADES DE.pdf

Dan,

I have attached the reports for the well survey and final well and sampling report.

Thank you

Connor O'Loughlin P.G.  
Environmental Protection Agency, Region III  
Site Assessment Manager, (3HS12)  
1650 Arch Street,  
Philadelphia, PA 19103-2029  
phone 215-814-3304  
Cell 412-779-0444

---

**From:** Taylor, Daniel <taylor.daniel@epa.gov>  
**Sent:** Monday, March 01, 2021 11:45 AM  
**To:** O'Loughlin, Connor <oloughlin.connor@epa.gov>  
**Subject:** Blades- MW1,2,3

Hey Connor,

We had our Site Visit with AECOM last week. While we were there, we walked around the Peninsula Plating area. We weren't able to find MW-1, MW-2, MW-2 shown on the 1999 SI report. During your Site Assessment, were you able to locate these? We were trying to get a sense of the MW inventory.

Daniel Taylor  
Remedial Project Manager  
DE; VA; WV Remedial Section  
Superfund Site Remediation Branch  
U.S Environmental Protection Agency  
Region III (3SD23)  
1650 Arch Street  
Philadelphia, PA 19103  
Office: (215) 814-3326  
Email: [taylor.daniel@epa.gov](mailto:taylor.daniel@epa.gov)